

Model	Model Code	Engine Code	Model Year	Core Size - Row	Core Location	Type	Hose Size	Aluminium Air Guide	Part Number	Retail Price (£+VAT)	Remarks
TOYOTA											
ARISTO	JZS161	2JZ-GTE	97/08-	200x200x32 · 15	Infront of radiator	S type	#10		15004-AT002	£ENQUIRE	
ALTEZZA	SXE10	3S-GE	98/10-	200x200x32 · 12	Inside right fender	S type	#10		15004-AT006	£ENQUIRE	Unconfirmed for AT. Fender protect required modification
SUPRA	JZA80	2JZ-GTE	93/06-	200x220x48 · 15	Inside left bumper	R type	#10		15004-AT003	£745.00	
CHASER	JZX100	1JZ-GTE	96/09-01/06	200x220x48 · 15	Inside left fender	S type	#12	0	15004-AT007	£ENQUIRE	Unconfirmed for Mark II and Cresta. Cannot be used with Stock washer tank
MARK II, CHASER	JZX100	1JZ-GTE	96/10-00/10	200x200x32 · 15	Infront of radiator	R type	#10		15004-AT004	£ENQUIRE	Unconfirmed for Cresta
MARK II, CHASER, CRESTA	JZX90	1JZ-GTE	93/10-96/09	200x180x48 · 12	Infront of radiator right	R type	#10		15004-AT005	£ENQUIRE	Cannot be fitted to vehicle 92/10~93/9
NISSAN											
SILVIA	S15	SR20DET	99/01-02/08	200x220x48 · 15	Inside right fender	R type	#10	0	15004-AN019	£ENQUIRE	Unconfirmed for AT. Not compatible with Super HICAS. Separate washer tanke required (Nissan part 27480-H1001)
SILVIA	S15	SR20DET	99/01-02/08	200x200x32 · 15	Infront of radiator	S type	#10		15004-AN018	£ENQUIRE	Unconfirmed for AT or Super HICAS
SILVIA	S15	SR20DET	99/01-02/08	200x200x32 · 15	Infront of radiator	R type	#10		15004-AN017	£ENQUIRE	Unconfirmed for AT or Super HICAS
SILVIA / 200SX	S14	SR20DET	96/07-98/12	200x220x48 · 15	Inside right fender	R type	#10	0	15004-AN016	£ENQUIRE	Unconfirmed for AT. Separate washer tanke required (Nissan part 27480-H1001)
SILVIA / 200SX	S14	SR20DET	93/10-96/06	200x220x48 · 15	Inside right fender	R type	#10	0	15004-AN015	£845.00	Unconfirmed for AT. Separate washer tanke required (Nissan part 27480-H1001)
SILVIA / 200SX	S14	SR20DET	93/10-98/12	200x200x32 · 15	Infront of radiator	S type	#10		15004-AN014	£577.50	
SILVIA / 200SX	S14	SR20DET	93/10-98/12	200x200x32 · 15	Infront of radiator	R type	#10		15004-AN013	£685.00	Not compatible with Super HICAS
SILVIA / 180SX	PS13, RPS13	SR20DET	91/01-98/12	200x200x32 · 15	Infront of radiator	R type	#10		15004-AN010	£731.50	RPS13 (94/1~98/12) requires electric fan removal. Unconfirmed for AT
180SX	RPS13	SR20DET	91/01-96/08	200x220x48 · 15	Inside right fender	R type	#10	0	15004-AN011	£ENQUIRE	Unconfirmed for AT. Separate washer tanke required (Nissan part 27480-H1001)
SKYLINE	ER34	RB25DET	98/05-00/07	200x200x32 · 15	Infront of radiator	S type	#10		15004-AN008	£525.00	Not compatible with AT models
SKYLINE	ECR33	RB25DET	93/09-98/04	200x200x32 · 15	Infront of radiator	S type	#10		15004-AN008	£525.00	Unconfirmed for AT or models with active LSD
SKYLINE GT-R	BNR34	RB26DETT	99/01-02/08	200x220x48 · 15	Inside left bumper	S type	#12	0	15004-AN005	£715.00	
SKYLINE GT-R	BCNR33	RB26DETT	95/01-98/12	200x220x48 · 15	Inside left bumper	S type	#12	0	15004-AN004	£715.00	models after 97/2 require oil cooler bracket (2599-SN002)
SKYLINE GT-R	BNR32	RB26DETT	89/08-94/12	200x220x48 · 15	Inside left bumper	S type	#12	0	15004-AN003	£715.00	
SKYLINE GT-R	BNR32	RB26DETT	89/08-94/12	200x160x32 · 12	Infront of radiator	R type	#10		15004-AN002	£ENQUIRE	
FUGA	PY50	VQ35DE	04/10-	200x200x32 · 15	Inside right fender	S type	#10	0	15004-AN020	£ENQUIRE	Bumper, inner fender and grill require modification for fitment. For GT grade cars.
FAIRLADY Z / 370Z	Z34	VQ37VHR	08/12-	200x220x48 · 15 x2	Infront of radiator + Inside left fender	S type	#10	0	15004-AN023	£ENQUIRE	Twin core kit. Cooling efficiency can be improved by modifying bumper protector, however correct operation of pop up hood cannot be guaranteed
FAIRLADY Z / 370Z	Z34	VQ37VHR	08/12-	200x220x48 · 15	Infront of radiator	S type	#10	0	15004-AN024	£ENQUIRE	Single core kit
FAIRLADY Z / 370Z	Z34	VQ37VHR	08/12-	200x220x48 · 15	Inside left fender	S type	#10	0	15004-AN025	£ENQUIRE	Single to twin core upgrade kit.
FAIRLADY Z / 350Z	Z33	VQ35DE	02/07-07/01	200x200x32 · 15	Inside right fender	S type	#10	0	15004-AN022	£725.00	Inner fender requires modification. Rear window washer cannot be used.
HONDA											
CIVIC TYPE R	EK9	B16B	97/07-00/08	200x160x32 · 12	Infront of radiator	S type	#10		15004-AH001	£ENQUIRE	
FIT / JAZZ	GD3	L15A	02/09-	200x120x32 · 9	Inside left fender	S type	#10		15004-AH002	£ENQUIRE	Inner fender requires modification.
MITSUBISHI											
LANCER EVOLUTION	CZ4A(X)	4B11	07/10-	200x220x48 · 15	Inside right bumper	Combine with Stock	#10	0	15004-AM013	£645.00	Stock oil cooler bracket and oil lines require modification. Cannot be used with stock fog lamps.
LANCER EVOLUTION	CT9A(IX)	4G63 MIVEC	05/03-	200x220x48 · 15	Inside left fender	Combine with Stock	#10	0	15004-AM010	£645.00	For HKS piping. Stock piping would require modification. Intercooler spray tank requires moving or changing
LANCER EVOLUTION	CT9A(VIII)	4G63	03/01-	200x220x48 · 15	Inside right bumper	Stock replacement	#10	0	15004-AM009	£645.00	Includes bumper side garnish
LANCER EVOLUTION	CT9A(VIII, VIII MR)	4G63	03/02-05/02	200x220x48 · 15	Inside left bumper	Combine with Stock	#10	0	15004-AM012	£645.00	Bracket requires modification when used with HKS piping kit.
LANCER EVOLUTION	CT9A(VII)	4G63	01/02-02/12	200x220x48 · 15	Inside right bumper	Stock replacement	#10	0	15004-AM008	£ENQUIRE	
LANCER EVOLUTION	CT9A(VII)	4G63	01/02-03/01	200x220x48 · 15	Inside left bumper	Combine with Stock	#10	0	15004-AM011	£ENQUIRE	Not compatible with GT-A models.
LANCER EVOLUTION	CP9A(VI)	4G63	99/01-01/01	200x220x48 · 15	Inside right bumper	Stock replacement	#10	0	15004-AM007	£585.00	
LANCER EVOLUTION	CP9A(V)	4G63	98/01-98/12	200x220x48 · 15	Inside right bumper	Stock replacement	#10	0	15004-AM006	£585.00	
MAZDA											
RX-8	SE3P	13B-MSP	03/05-	200x200x32 · 15	Inside right fender	Combine with Stock	#10	0	15004-AZ003	£ENQUIRE	
RX-7	FD3S	13B-REW	91/12-98/12	200x220x48 · 15	Inside fender L/R	Stock replacement	#10	0	15004-AZ002	£ENQUIRE	Twin core. For MT models.
EUNOS ROADSTER / MX-5	NA6CE	B6ZE	89/09-93/07	200x160x32 · 12	Infront of radiator	S type	#10		15004-AZ004	£ENQUIRE	Unconfirmed for AT models.
SUBARU											
IMPREZA	GRB	EJ20	07/10-	200x175x48 · 12	Inside right bumper	S type	#10	0	15004-AF010	£795.00	Racing Suction Reloaded (available seperately) is required. Due to lack of clearance, oil pressure/temperature sendors can not be fitted.
IMPREZA	GC8, GF8	EJ20	92/11-97/08	200x200x32 · 15	Infront of radiator	S type	#10		15004-AF004	£585.00	Due to lack of clearance, oil pressure/temperature sendors can not be fitted.
IMPREZA	GDB	EJ20	05/06-	200x200x32 · 12	Inside bumper	S type	#10	0	15004-AF007	£645.00	For model year code F. Not compatible with SPEC-C. Combines with water cooled oil cooler. Due to lack of clearance, oil pressure/temperature sendors can not be fitted. Stock fog lamps cannot be used.
IMPREZA	GDB	EJ20(TURBO)	02/11-05/07	200x200x32 · 15	Inside bumper	S type	#10	0	15004-AF006	£665.00	For model year codes C-E. Due to lack of clearance, oil pressure/temperature sendors can not be fitted.
IMPREZA	GDB	EJ20(TURBO)	00/10-02/10	200x200x32 · 15	Inside bumper	S type	#10	0	15004-AF005	£731.50	For model year code A-B. Combines with water cooled oil cooler. Due to lack of clearance, oil pressure/temperature sendors can not be fitted. Stock fog lamps cannot be used.
IMPREZA WRX Sti	GDB(F)	EJ20	05/06-						15004-AF007	£645.00	
LEGACY TOURING WAGON	BP5	EJ20X	03/05-	200X200X32 · 12	Infront of radiator	R type	#10		15004-AF008	£ENQUIRE	For AT models. Model year code A-C
LEGACY TOURING WAGON	BP5	EJ20Y	03/05-	200X200X32 · 12	Infront of radiator	R type	#10		15004-AF009	£ENQUIRE	For MT models. Combines with stock watercooled oil cooler. For model year codes A-C
LEGACY B4	BL5	EJ20X	03/05-	200X200X32 · 12	Infront of radiator	R type	#10		15004-AF008	£ENQUIRE	For AT models. For model year codes A-C
LEGACY B4	BL5	EJ20Y	03/05-	200X200X32 · 12	Infront of radiator	R type	#10		15004-AF009	£ENQUIRE	For MT models. Combines with stock watercooled oil cooler. For model year codes A-C
SUZUKI											
SWIFT SPORT	ZC31S	M16A	05/09-	200x120x32 · 9	Inside left fender	R type	#10		15004-AS001	£815.00	
DAIHATSU											
COPEN	L880K	JB-DET	02/06-	200x120x32 · 9	Inside left bumper	R type	#10		15004-AD001	£ENQUIRE	No thermostat
VOLKSWAGEN											
GOLF	1KA XX	AXX, BWA	05/06-	200x175x48 · 12	Inside left fender	Stock replacement	#10		15004-LW001	£845.00	Modification of inner fender required. No thermostat. Cannot be used with models with sub radiator (MY2005)

*PLEASE NOTE THAT THE ABOVE FITMENTS ARE FOR JAPANESE SPECIFICATION VEHICLES. EUROPEAN OR UK SPECIFICATION VEHICLES MAY NOT BE COMPATIBLE WITH THE ABOVE PARTS. PLEASE CONTACT YOUR LOCAL DEALER FOR INFORMATION.